## REMEDIAL SITE ASSESSMENT DECISION - EPA REGION II

State ID#:

City: Bioomneio	County or Parisn: Essex	State: NJ		
Refer to Report Dated: 95/07/12	Report type: SIP			
Report developed by: <u>EBASCO</u>				
DECISION:				
X   1. Further Remedial Site	Assessment under CERCI	A (Superfund) is not required	because:	
site assessment	qualify for further remedial under CERCLA nedial Action Planned - NFR	1b. Site may quali action, but is AP)	- <del>-</del>	

DISCUSSION/RATIONALE: The Peerless Tube Corporation (PTC) site is located in Bloomfield, Essex County, New Jersey. The 4-acre site contains an active facility which manufactures aerosol cans and squeeze tubes. Its activities generate wastes which contain mainly paints and chlorinated organics. The groundwater pathway score is based on an observed release to an on-site monitoring well. The nearest well is located between 0.25 and 0.50 mile from the site. No contaminant release has been documented to these wells. The surface water pathway score is based on a potential-to-release basis. No release of contamination to any of the adjacent waterbodies has been documented. The soil pathway score is based on contamination in surface soil at the site. Analytical results of surface soil samples indicate contamination exists within 2 feet of the surface; however, there is no documentation for migration of contaminants from the sampled locations. There are no nearby day-care facilities or terrestrial sensitive environments, on or within 200 feet of the contaminated soil. The air pathway score is based on a potential-to-release basis. An observed release of contaminants via the air has not been documented.

Reviewed by: T. Basu

Site Decision

Made by: Joseph Hudek

Cionatura

Site Name: Peerless Tube EPA ID#: NJD002171122

2. Further Assessment Needed Under CERCLA:

2a. Priority: | | Higher | | Lower

2b. Other: (recommended action) None

Alias Site Names:

Date: 95/8/16

EPA Form # 9100-3